

## Step 1

Lay floor panels (open hole sockets) in position and place legs as shown. (Make sure legs go through to ground).

## Step 2

Position the **(2) middle panels** (closed hole sockets) on **12" legs** overhanging outside edges as shown. Push down until leg rests on top of socket.

## Step 3

Position the top panel (closed hole sockets) on 24" legs using inside row of sockets as shown. Push down until leg rests on top of socket.



- 3401 Chief Drive - Holly, Michigan 48442-9333 - Phone (810) 953-9400 - Fax (810) 953-9440 **1-800-523-6899** sm66-962403p3\_inst/0299