

Components: Panels:

ASSEMBLY INSTRUCTIONS SM967209PI

Oil All Sockets Before Assembly

Fully Assembled

Page 1









Floor Level Place legs as shown. Push legs through to ground.





Position (2) Level 1 Panels on 12" legs overhanging outside edge as shown.



- A. Invert Level 2 panel and place (2) 12" legs in outside closed sockets.
- B. Position center sockets of panel on 24" legs while placing 12" legs on the Level 1 panel. Push panel down so that the 24" legs are seated in the center sockets as shown.



Step4 Level 3

Position center sockets of 3rd Level panel on 36" legs while panel over hangs level 2. Push panel down so that the 36" legs are seated in the sockets.





Step 6

Plant Hanger Legs

Remove plant hanger tops and insert 72" legs into outside open hole sockets of Level 3 and 2. Slide legs all the way through open hole sockets in floor panels. (Make sure to push legs all the way down to the floor).



- 3401 Chief Drive - Holly, Michigan 48442-9333 - Phone (810) 953-9400 - Fax (810) 953-9440 1-800-523-6899 sm967209pi_inst/0607 Copyright © 2007 All rights reserved.

Step 7

as shown.

PATENT PENDING

Plant Hanger Assembly

nsert Plant hange assembly in 72" legs

Plant Hanger Tops





Lower Level Invert 5' Lower Panel and place (5) 12" legs in sockets as shown.



Step 2

Lower Level

Turn over and slide (3) 24" legs through sock-

ets A,B and C as shown. (Push legs all the way

B

0

0 0







PATENT PENDING